Philco Radio & Television Corp.			
	Model: 37-61	Chassis:	Year: Pre October 1937
	Power:	Circuit:	IF:
	Tubes:		
	Bands:		
Resources			
Riders Volume 8 - CHANGES 8-3			
Riders Volume 7 - PHILCO 7-23			
Riders Volume 7 - PHILCO 7-24			
Riders Volume 7 - PHILCO 7-25			

Philco 37-600

To prevent reduction in sensitivity at the low-frequency end of the band, the 200-ohm resistor, No. 7, has been changed to 300 ohms, starting with Run No. 3. This change has been noted in the Parts List on page 7-37 of Rider's Volume VII, but it still shows as 200 ohms on the schematic, which will be found on the same page.

The lead connecting the suppressor grid to the cathode of the 6J7G i-f tube has been changed. It now runs from the suppressor grid to the junction of the sensitivity control, No. 23, and the secondary of the i-f transformer, No. 19.

Philco 37-116

Up to Run No. 4, a condenser was connected between the heater contact and ground of the 6K7G r-f tube. This condenser was removed starting with Run No. 4 to prevent hum modulation on Range 5. It is not shown on the schematic appearing on page 7-31, 7-32 of Rider's Volume VII.

Electrolytic condensers, Nos. 126 and 127, 8 mf., have been changed to 4 mf. Part No. 30-2174, starting with Run. No. 5.

Starting with Run No. 6, the two 25,000-ohm resistors, Nos. 110 and 111, have been removed from the audio unit and relocated in the power unit near the 6B4G sockets.

To obtain the proper selectivity curve in the expanded position of the i-f expanding unit and to avoid regeneration, dress the plate lead (white) of the 6L7G tube as follows: The plate lead should lay across the 6L7G socket, then pass into the oscillator section close to the base; from here the wire must pass through the second aperture from the front of the r-f unit into the i-f unit.

To prevent clicks when tuning the bass compensation control on a very strong carrier, a 2-megohm resistor, Part No. 33-520339, was connected from the lug on which the 70,000-ohm resistor, No. 103, and the .008-mf. condenser, No. 104, are connected in the audio unit, to ground.

It will be noticed in the schematic on page 7-31, 7-32 of Rider's Volume VII, that two parts carry the same number: No. 135. One is the pilot light and this is the correct number for this part; the second is a switch, located on the schematic just below and to the left of the 6J5G AVC tube. The number of this switch should be 137. This number does not appear in

one list of parts on page 7-36, but the switch is used on the automatic dial mechanism and appears in the parts list under "Code 122" as "Plunger Stop and Switch Assembly, Part No. 45-2330."

Another switch located betwen Nos. 100 and 103 on the schematic with the wording "used in code 122 only," is used to short the audio system when using the automatic dial. This switch is located on the vernier drive assembly. The part numbers of the removable sections which contain the riveted contacts, are 45-2350 and 28-4110.

The magnetic tuning transformer has been changed. Its old part number was 32-2217 and its new number is 32-2361.

Philco 37-38

Starting with Run No. 4, the filament wiring of the 1D5G i-f. tube was reversed to improve the operation of the set. In Fig. 1 on page 7-18 of Rider's Volume VII, the "F+" of the 1D5G socket becomes "F-" and is grounded to the lug near the socket.

The 32,000-ohm resistor, No. 8 (see schematic on page 7-17 of Rider's Volume VII) has been replaced with one having a value of 51,000 ohms, Part No. 33-351339. The resistor is removed from the range switch assembly and is connected directly to the oscillator grid of the 1C7G tube and prove the sensitivity in the center of the broadcast band.

Philoo 37-60

Run No. 2. The 1000-mf. condenser, No. 11, was changed to 250 mmt., Part No. 30-1032, and resistor No. 12 was changed from Part No. 33-351339 to No. 33-332339. This change was made to prevent relaxation oscillation.

Run No. 5. Refer to the Base View of the chassis on page 7-22 of Rider's Volume VII. The condenser No. 46 has been moved from the location shown—near the front—to the rear of the power unit. The tubular condenser No. 40 has been replaced with Part No. 8318-SU Bakelite condenser and mounted in the location from which No. 46 was removed.

Run No. 6. The suppressor grid of the 6K7G, i-f tube, is removed from ground and connected to the —2.5 negative tap of the bias resistor, No. 43. See schematic on page 7-19 of Rider's Volume VII.

Beginning with Run No. 9, the i-f transformers were changed. The first i-f transformer No. 15 now is Part No. 32-2274 and the second, No. 27, is Part No. 32-2276. The first i-f transformer has a stabilizing winding which is placed in series with the suppressor grid of the 6K7G i-f tube. The short or yellow lead is connected to the ground lug and the long lead to the suppressor grid.

Philco 37-61


The changes applying to Philco Model 37-60 also apply to Model 37-61 with the exception of the first paragraph. The schematic diagram appears on page 7-23 in Rider's Volume VII.

Philco 90, 90A

Please make a note on page 84 of Aligning Philco Receivers that the i-f. peak of both chassis used in these models (with two 45s and one 47) is 175 kc. Note 1 on this page should read "175 kc. for both chassis." The correct i-f. peak is indicated on the schematics in Rider's Manuals.

Wells-Gardner 6K Series


If noise (not motor or vibrator) is encountered in this model, it may be due to the fact that the antenna transformer shield can is not grounding satisfactorily. The noise brought about by this condition is a popping or scratching, and will be heard only when the chassis is bumped or shaken.




By inserting a spring as shown above in the Wells-Gardner 6K series chassis, a good ground is assured for the antenna transformer shield.

This condition can easily be remedied without removing the chassis from the case by inserting a phosporbronze spring between the antenna coil can and the chassis bracket. This spring is inserted with a pair of longnose pliers and the position after insertion is shown in the illustration.

For other data, see pages 7-20 and 7-21 in Rider's Volume VII.





Compensators Top of Chassis Adjustment of Compensators

Fig. 3-Locations of I. F.

generator ground lead to GND. TERMINAL No. 3, rear of chassis. Connect TERMINAL No. 2 to GROUND TERMINAL No. 3 with connector link provided on the panel.

Fig. 4-Locations of R. F.

Compensators Underside of Chassis

Oscillator Circuit; and two in the Antenna Circuit. Incorrect 2 Set range switch in position No. 2 (S. W.). Turn signal generadjustment will cause loss of sensitivity, unsatisfactory tone, and adjust compensator (7) Osc. for maximum output.

To accurately adjust this receiver, precision test equipment is 3 necessary. A signal generator such as the PHILCO MODEL 088 SIGNAL GENERATOR, covering from 110 to 20000 K. C. The adjustment of the antenna compensator on the high frequency range causes a slight detuning of the oscillator circuit. In order to overcome this detuning effect, connect a variable condenser of approximately 350 mfd., having a good vernier drive, across the oscillator section of the tuning condenser. Leaving the signal generator and receiver dials at 18 M. C., turn the added condenser as that the receiver dials at 18 M. C., tune the added condenser so that the second harmonic of the receiver oscillator will beat against the signal from the signal generator. The antenna compensator (3a should then be adjusted to give maximum output.

Now remove the external condenser from the tuning condenser of receiver and turn compensator 7 osc, to the maximum capacity position (clockwise), then without moving signal generator or receiver tuning condenser, turn compensator () (counter-clockwise) until a second peak is reached on the output meter. The first peak is caused by tuning to the image frequency signal and must be neglected. Compensator ① is adjusted on the second peak to give maximum output.

No. 27-7059 complete the necessary equipment for these adjust-4 The locations of the various compensators are shown in Figs. 3 and 4.

Philco Fibre Wrench No. 3164 and Fibre Handle Screw-driver

is recommended to adjust the compensators at the various frequencies specified. A visual indication of the receiver output is also necessary to obtain correct adjustment of the compensators. PHILCO MODEL 025 CIRCUIT TESTER contains a very sensitive output meter and is recommended for these adjust-

The accurate adjustment of the various compensating con-ensers is vital to the proper functioning of this receiver. There densers is vital to the proper functioning of this receiver. There are four compensating condensers in the I. F. Circuit; three in the

The following procedure must be observed in adjusting the compensators:

DIAL ADJUSTMENT—The Tuning Condenser is set at the maximum capacity position, by turning the tuning knob counterclockwise. Loosen the set screw of dial hub and set dial, (see Fig. 2) with Glowing Indicator centered between the index lines RANGE 1: 530 to 1720 K. C. at the low frequency end of scale.

OUTPUT METER—The Output Meter is connected to the Plate and Cathode terminals of the (6F6G) tube and adjusted to use the (0-30) Volt scale. When adjusting each circuit, care should be taken to have the Signal Generator attenuator set to give approximately ¼ scale reading on output meter.

INTERMEDIATE FREQUENCY CIRCUIT

Fig. 2-Dial Calibration

poor selectivity.

- 1 Turn range switch to Range 1. Rotate the tuning control to approximately 600 K. C. Connect the 088 Signal Generator output lead through a .1 mfd. condenser to the grid of the 6A8G tube.
- Set Signal Generator indicator for 470 K. C. adjust attenuator for approximately 1/2 scale reading on output meter. Then adjust compensators 28a 2nd I. F. Sec., 28 2nd I. F. Pri., (0a 1st I. F. Sec., (1) 1st I. F. Pri., for maximum reading on output

RADIO FREQUENCY CIRCUIT Range 2.-5.7 to 18 M. C.

Remove the signal generator output lead and series condenser from the 6A8G tube and connect them to the ANT. TERM-INAL No. 1, on aerial input panel (rear of chassis) and the

Turn range switch to Range No. 1. Turn the Receiver dial to 1600 K. C. Then adjust compensators (§) and (§) for maximum reading on output meter.

The 088 Signal Generator dial is set at 800 K.C. and the second harmonic of this frequency (1600 K. C.) is used in making the above adjustment.

- The low frequency end of the band is now tuned by turning Signal Generator and Receiver dials to 600 K. C. and adjusting compensator (§a—see note (a) below—for maximum output.
 - When compensator ®a osc. series is being adjusted, the Tuning Condenser must be rolled for maximum output. This is accomplished as follows: First tune compensator a for maximum output. Then vary the Tuning Condenser for maximum output at 600 K. C. Now retune Compensator ®a and again vary the tuning condenser back and forth at 600 K. C., for maximum output. This operation of first tuning the Compensator, then the Tuning Condenser is continued until maximum output is obtained at the 600 K. C. frequency.
- 3 Set the Signal Generator and Receiver Dials for 1600 K. C. and re-adjust Compensator ® for maximum output. Then turn the dials to 1500 K. C. and re-adjust compensator ® for maximum reading on output meter.


Transformer Data Notes, Parts

PHILCO RADIO & TELEV. CORP.

MODEL 37-61 Chassis, Voltage

Model 31-01 is a 5 tube superheterodyne receiver for operation on alternating current and has two tuning ranges, covering standard broadcast and short wave reception. It, also, uses the new Philco High Efficiency self-centering glass tubes.

The circuit includes the Philco Foreign Tuning System—controlled by the range switch—providing maximum sensitivity and noise reduction when used with the New Philco High-Efficiency Aerial, supplied with the receiver.



8-9

6.7

2.1A

Fil.

Black

.1 ohm

Measurements taken with PHILCO MODEL 025 Circuit Tester which contains a 1000 ohms per volt Voltmeter. Line voltage, 115—Range Switch in Broadcast Position. Dial tuned to **600 K**. C.