




Sears Roebuck & Co.

	Model: 6068	Chassis:	Year: Pre August 1939
	Power:	Circuit:	IF:
	Tubes:		
	Bands:		
Resources			
Riders 10 (X) SEARS 10-45			
Riders 10 (X) SEARS 10-46			



LOCATIONS OF PARTS ON TOP OF CHASSIS.

57RL 108
JUNE 16 1938

MODELS 6008,6009,6018
6019,6048,6049,6068,6069
6148,6168,Ch. 101,524
Chassis Layout,Data

SEARS-ROEBUCK & CO.Socket,Trimmers,Chassis
Notes

MODELS 6010,6040,Ch.101,519

BATTERY REPLACEMENT:

The dry cell volt "A" battery should be replaced when its voltage drops to 3.4 volts, under load. The six volt "B" battery should be replaced when the voltage of the battery has dropped to 48 volts, under load. The life rating of the various size batteries, given on the next page, are for an average use of three hours a day.

