| Philco Radio & Television Corp. | | | | | |
|---------------------------------|----------------|-----------|----------------------|--|--|
| | Model: 16A-123 | Chassis: | Year: Pre March 1934 | | |
| | Power: | Circuit: | IF: | | |
| | Tubes: | | | | |
| | Bands: | | | | |
| | | Resources | | | |
| Riders Volume 4 - Pl | HILCO 4-8 | | | | |

MODEL 16,16A-122, 164-123 Changes

PHILCO RADIO & TELEVISION CORP.

Model 16

Effective with current production, Toggle Switch (Interstation Noise Suppression Circuit) @, Part No. 42-1036, is superseded by Toggle Switch Part No. 3253. and two Part No. 9618 leads, in Model 16-123; by Toggle Switch Part No. 3253, one Part No. 9616 lead and one Part No. 9617 lead, in Model 16-121 and 16-122. The joint at the switch is protected by two pieces of sleeving. The list price of Switch, Part No. 3253, is 40 cents.

Effective with current production, Knob Part No. 03063 will be used upon Wave-Band Switch @, in lieu of knob Part No. 03064, upon Models 16-121, 16-122 and 16-123. Tuning Condenser Assembly @ will use Knob Part No. 42-4025, Volume Control and "On-Off" Switch @ will use Knob Part No. 03064, and Tone Control @ will use Knob Part No. 03064.

Model 16

Refer to Service Bulletin No. 165

Effective with Run Number 3, the following substitutions were made in the by-pass condensers:

A Part No. 3615-AT superseded by Part No. 3615-BK, list price, \$0.16
Part No. 3615-D superseded by Part No. 3615-BL, list price, 0.16
Part No. 3615-AT superseded by Part No. 3615-BK, list price, 0.16

NOTE: The electrical values of these condensers remain the same.

Effective with Run Number 2, Resistor @ Part No. 6977 (500 ohms) (Green-Black-Brown) is superseded by Resistor Part No. 33-3010 (300 ohms) (Orange-Black-Brown). Both are flexible wirewound. The *list* price of Part No. 33-3010 is \$0.15.

The large keob now used upon Tuning Condenser Assembly 3 bears Part No. 27-4025, instead o 42-4025. Make this correction to Service Bulletin No. 170; Page 2, line 5.

The following additional list prices should be included in the Replacement Parts list:

| No. on Figures | Description Part | List Price |
|--------------------|---|-----------------|
| (a) Wave Trap Asse | mbly | \$0.30 |
| | ermer (B'de'st & Police Bands) | .60 |
| | ble) | .30 |
| Speaker Field, A | ssembled with Pot, (U-2) | 6.75 |
| (NOTE | : The above four list prices are effective September 15, 1933). | |
| This additiona | l list price should be included in the Replacement Parts list: | |
| No. on Figs. | Part Pescription No. | List |
| | Description No | Price \$0.19 |
| Note: The a | bove list price is effective September 15, 1933. | |

Models 16A-122 and 16A-123

(25 cycle sets)

Effective December 14, 1933, all production on these models will have the first electrolytic condenser ©, part No. 30-2014 superseded by part No. 30-2067, no change in connections. (No. 30-2014 is 8 mfd. 500 volt, and 30-2067 is 10 mfd. 15 volt.)

| | The following additional list prices should be included in the Replacement Parts list: | | | | | |
|-------------|--|---------|---------------|--|--|--|
| No. FIGU | ON JRES DESCRIPTION | PART | List Price | | | |
| ① | Wave Band Switch | 42-1037 | \$2.75 | | | |
| ҈ ③ | Tuning Condenser Assembly | 31-1030 | .40 | | | |
| (B) | Compensating Condenser (2nd. I. F. Pri.) | 21_6009 | .35 | | | |
| (i) | Compensating Condenser (3rd. I. F. Pri.) | 31-6002 | .35 | | | |
| (60) | Output Transformer | 29-7059 | 1 50 | | | |